



### Visitor Centre and Lodge

Extension of existing Lodge to create multi-use spaces including meeting and research rooms, for visitors, educational groups and the wider community along with a garden area for displays and interpretation. Improved accommodation and reception areas for the Bereavement Services.



### Infrastructure repairs

Re-construction of carriageways to an appropriate high quality standard with associated drainage repairs.



### Robson Road Entrance

New pedestrian entrance, with enhancements to the streetscape, (subject to landowner agreements).



### St Stephen's Chapel

Conservation and repair of the Chapel, including the incorporation of services and toilets to enable use for a wide range of events, displays, and functions. Improved access.



### Boundary repairs

Repairs and conservation of boundary railings and gates.



### Grass management

Continue to manage selected areas to improve bio-diversity and wildflowers.



### Enhanced views

Continue to manage trees, including sycamore and ash, to open up key views.




### Monument repairs

Conserve and stabilise selected monuments, along important paths (Ship, Beeton and Doulton paths).



### Hubbard Road Entrance

Re-instate gates as pedestrian entrance, with enhancements to the streetscape, (subject to agreements with grave owners).



### Conservation of Listed Monuments

Repairs and stabilisation of 16 significant Listed monuments deemed "heritage at risk".



### Infrastructure repairs

Re-construction of path and drainage (St Mary at Hill path).



### Path Improvements

Improve drainage and surfacing, with an informal gravel finish (Doulton path).



### Ongoing management

Continue to manage and control scrub to improve bio-diversity, protect monuments, and enable better access to graves.

